

Corner originally set as a post in 1820 by John Hendricks with the following witnesses: 18" beech bearing south 59 degrees, thence east 3 links; and a 20" hickory bearing north 44 degrees, thence west 49 links. (M.C. Atlas p. 11) A survey by D.B. Hasbrook on June 2, 1851 indicates no stone but the following witness: 32" elm bearing south 22 degrees, thence west 138 links.(Warren Legal Book p. 7) Corner referenced by Wilcoxen on 9/18/75 and called a road nail over steel plate. Corner referenced by Gries on 11/30/87 and called a road nail over steel plate. Corner referenced by Kiste on 7/5/95 and called a pk nail with washer. Corner referenced by Kiste on 9/1/05 and called a pk nail with washer. Corner excavated by Wilcoxen on 8/11/08 and a 8" steel plate was found 4" down. No other points were found. A #205 cast iron Harrison Monument was set in position of the steel plate.

	1604340	
REF.	DISTANCE	DESCRIPTION
1.	57.09	Cut 'x' SW corner of inlet
2.	18.29'	Due E to NW corner of 3-15-4 (Harrison)
3.	67.44'	Cut 'x' SW bolt of aluminum pole base
4.	42.32'	Cut 'x' NE bolt of aluminum pole base
5.		Top nut of fire hydrant
6.	40.97	Mag nail w/bw E PwP#245-513 3" up
maja, majada	I I	